



Oswestry.. ive attached an image of the north west corner of field KCK 009 in knockin... north of church lane, knockin..

I couldnt put this image on forms A&B.. this flooding was last visible in 2014.. but also the flooding is every year along the east aspect of the field along the weirbrook... this field is lower than the brook which is buffered... i feel drainage will be compromised and sewage treatment is already over subscribed in the reedbed plant north end of church lane.

with regards Guy Jones